

Arnold Palmer Bay Hill Club, Florida



Dirt, Mold & Mildew

Arnold Palmer Bay Hill Club sweeps across 270 acres along the shores of the Butler Chain of Lakes. Bay Hill is showcased each spring as one of the most popular stops for the PA TOUR® .

The Clubhouse entry way is laid with slate and prior to sealing with Glass Fusion™ the maintenance people would have to pressure wash every other day with harsh chemicals to keep the slate and grout clean. The entry way was very susceptible to dirt, mold and mildew growth from the humid weather in Orlando.

GFI sealed the slate with Glass Fusion™ NS100 Natural Stones Sealer. This provided a durable barrier for the stone to withstand dirt, the growth of mold and mildew on the slate and grout joints. The Natural Stone Sealer enhanced and deepened the natural colors of the slate and gave it a beautiful gloss. The slate entry way is now cleaned only before a tournament.